

Newmarket-Tay Power Distribution Ltd.

Major Event Day: September 4, 2020

RRR 2.1.4.2.10 Major Event Response Reporting

When a distributor determines an outage was caused by a Major Event, it shall file a report with the OEB that outlines the distributor's response to the Major Event, including answers to all of the auestions set out below. Distributor responses are identified in the text boxes below.

A distributor shall file this report with the OEB within 60 days of the end of the Major Event unless there are exceptional circumstances, in which case the report can be filed within 90 days of the end of the Major Event.

Prior to the Major Event

| |Yes

1. Did the distributor have any prior warning that the Major Event would occur?

🛛 No Additional Comments:

2. If the distributor did have prior warning, did the distributor arrange to have extra employees on duty or on standby prior to the Major Event beginning?

🗌 Yes	🗌 No	🖂 N/A
-------	------	-------

Brief description of arrangements, or explain why extra employees were not arranged:

3. If the distributor did have prior warning, did the distributor issue any media announcements to the public warning of possible outages resulting from the pending Major Event?

🗌 Yes	🗌 No	🖂 N/A
-------	------	-------

Did the distributor train its staff on the response plans to prepare for this type of Major 4. Event?

🛛 Yes	🗌 No
-------	------

During the Major Event

Please identify the main contributing Cause of the Major Event as per the table in section 1. 2.1.4.2.5 of the Electricity Reporting and Record Keeping Requirements.

 \boxtimes Loss of Supply

Lightning

Adverse Weather-Wind

Adverse Weather-Freezing Rain/Ice Storm

Adverse Weather-Snow

Adverse Environment-Fire

Adverse Environment-Flooding

☐ Other

Please provide a brief description of the event (i.e. what happened?). If selected "Other", please explain:

Transmitter reported high winds caused a tree contact on overhead feeder line supplying Newmarket-Tay Power service area.



- 2. Was the IEEE Standard 1366 used to derive the threshold for the Major Event?
 - Yes, used IEEE Standard 1366
 - No, used IEEE Standard 1366 2-day rolling average
 - No, used fixed percentage (i.e., 10% of customers affected)
- 3. When did the Major Event begin (date and time)?

September 4, 2020 at 2:59 PM

4. Did the distributor issue any information about this Major Event, such as estimated times of restoration, to the public during the Major Event?

🛛 Yes 🛛 🗌 No

If yes, please provide a brief description of the information. If no, please explain:

Yes, an outage notification with an estimated time of restoration was made available to the public on the distributor's website and Twitter account.

5. How many customers were interrupted during the Major Event?

7,923 Customers

What percentage of the distributor's total customer base did the interrupted customers represent?

<u>18</u> %

6. How many hours did it take to restore 90% of the customers who were interrupted?

2.05 Hours. Additional Comments: 100% were restored in 2.05 hours.

7. Were there any outages associated with Loss of Supply during the Major Event?

If yes, please report on the duration and frequency of the Loss of Supply outages:

Yes, the full duration of the Major Event was caused by a Loss of Supply.

8. In responding to the Major Event, did the distributor utilize assistance through a thirdparty mutual assistance agreement with other utilities?

Yes

🛛 No

Do not have third party mutual assistance agreements with other utilities

If yes, please provide the name of the utilities who provided the assistance?

9. Did the distributor run out of any needed equipment or materials during the Major Event?

🗌 Yes 🛛 🖾 No

If yes, please describe the shortages: ____



After the Major Event

- 1. What actions, if any, will be taken to be prepared for, or mitigate, such Major Events in the future?
 - \boxtimes No further action is required at this time
 - Additional staff training
 - Process improvements
 - System upgrades
 - Other

Additional Comments:

Major Event was due to tree contact on transmitter owned equipment, therefore no further action is required by NT Power at this time.